

SmartSensor Cable	Click! 200 Unprotected Connection	Description
Black	-DC	-DC (0V, DC GND)
Red	+DC	+DC (12-24 VDC Input)
Power Drain	GND next to +/-DC	Power Shield
RS-232 Drain	GND next to +/-DC	RS-232 Shield
Blue	-485	RS-485 Negative
White	+485	RS-485 Positive
RS-485 Drain	GND next to +/- 485	RS-485 Shield and Signal GND
Grey	GND next to +/- 485	RS-232 GND
Yellow	TD	TD (RS-232 Output from sensor)
Violet	RD	RD (RS-232 Input to sensor)
Brown	CTS	CTS (RS-232 Handshaking input to sensor)
Orange	RTS	RTS (RS-232 Handshaking output from sensor)

* For short cable runs (~ <50') connect the sensor to the Unprotected Side of the Click! 200.